

FIG. 1
(Prior Art)





FIG. 7

FIG. 2
(Prior Art)





FIG. 8




FIG. 4
(Prior Art)




FIG. 10




FIG. 3
(Prior Art)




FIG. 9

Axial
Conductance
(L/s)





FIG. 5
(Prior Art)

Axial
Conductance
(L/s)



Axial Gap (Inches)

FIG. 11




FIG. 6
(Prior Art)




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17